

TRIUMPH & LUCAS PART NUMBERS

05-27 Headlamps Left Hand Steer (LHS) - except France & USA	Part No				
	Triumph	Lucas			
		1971	1972	1973	1987 Supersession
Headlamp rim	511598	54520356			54524588
Headlamp rim	511598		54524588	54524588	
Rim seating assembly	518044	54523537			Obsolete
Rim seating assembly	518044		54524590	54524590	54528182
Body		54520207			
Body			54525488	54525488	
Inner main beam headlamp assembly	311841	59986A/B			LLB410 61154
Inner main beam headlamp assembly	311841		60215	60215	LLB410 61154
Inner main beam sealed beam unit	GLU105				
Inner main beam headlamp light unit		54524269	54524269	54524269	LUB220
Rim seating assembly	518082	54523538			Obsolete
Rim seating assembly	518082		54524589	54524589	
Outer dipped beam headlamp assembly	311831	59988A			LLB410 61153
Outer dipped beam headlamp assembly	311831		60216	60216	LLB410 61153
Outer dipped beam light unit	518817	54524078	54524078	54524078	LUB210
Bulb retaining spring		54522993	54522993	54522993	Not Serviced
Bulb		410	410	410	LLB410
Sealing sleeve	518081	54524040			
Sealing sleeve	518081		54524720	54524720	Not Serviced
Gasket	511602	54520217	54520217	54520217	Not Serviced
Screw	507086	186137	186137	186137	Not Serviced