

TRIUMPH & LUCAS PART NUMBERS

05-28 Headlamps Left Hand Steer (LHS) - USA	Part No				
	Triumph	Lucas			
		1971	1972	1973	1987 Supersession
Headlamp rim	511598	54520356			54524588
Headlamp rim	511598		54524588	54524588	
Rim seating assembly	518044	54523537			Obsolete
Rim seating assembly	518044		54524590	54524590	54528182
Body		54520207			
Body			54525488	54525488	
Inner main beam headlamp assembly	311842	58602A/H	58602	58602	
Inner main beam sealed beam unit	511606			54521334	SB4001
Rim seating assembly	518082	54523538			Obsolete
Rim seating assembly	518082		54524589	54524589	54528181
Outer dipped beam headlamp assembly	311832	58603A/H	58603	58603	
Outer dipped beam sealed beam unit	511607			54521335	SB4002
Screw	507086	186137	186137	186137	Not Serviced
Adaptor		553738	553738	553738	
Sealing sleeve	518014	54520216			Not Serviced
Sealing sleeve	518014		54524720	54524720	Not Serviced
Gasket	511602	54520217	54520217	54520217	Not Serviced