

TRIUMPH & LUCAS PART NUMBERS

05-33 Stop/Tail/Flasher & Reverse & Rear Marker Lamps USA	Part No				
	Triumph	Lucas			
		1971	1972	1973	1987 Supersession
Rear lamp unit - RH, to LD20001	217627	56191A	56191A		Not Serviced
Rear lamp unit - RH, from LD20001	TKC332			56510A	Not Serviced
Rear lamp unit - LH, to LD20001	217626	56192A	56192A		Not Serviced
Rear lamp unit - LH, from LD20001	TKC331			56511A	Not Serviced
Lens assembly		54581637	54581637	54581637	Not Serviced
Bulb holder - reverse light	518042	54577578	54577578	54577578	
Bulb - reverse light	519313	382	382	382	LLB382
Bulb holder - stop/tail light	518041	54577579	54577579	54577579	
Bulb - stop/tail light	GLB380	380	380	380	LLB380
Bulb holder - indicator light	518042	54577578	54577578	54577578	
Bulb - indicator light	GLB382	382	382	382	LLB382
Gasket - lamp to body	216126	54579144	54579144	54583251	Not Serviced
Rear side marker lamp	156949	52948A or 56274A			Not Serviced
Rear side marker lamp	156949		56274A	56274A	Not Serviced
Reflex reflector assembly	520351	54579805			Not Serviced
Reflex reflector assembly	520351		54582782	54582782	Not Serviced
Marker lens assembly	518802	54579804	54579804	54579804	Not Serviced
Lens seating gasket	518803	54579081	54579081	54579081	Not Serviced
Lamp seating gasket	520352	54579080	54579080	54579080	Not Serviced
Lamp fixing clamp	152013	54579082	54579082	54579082	Not Serviced
Washer	503581	188330	188330	188330	Not Serviced
Nut	515049	54579082			Not Serviced
Nut	515049		54131266	54131266	
Bulb holder	518807	54575976	54575976	54575976	Not Serviced
Bulb	GLB504	504	504	504	LLB504