

TRIUMPH & LUCAS PART NUMBERS

05-44 Steering Column Switches	Part No				
	Triumph	Lucas			
		1971	1972	1973	1987 Supersession
Windscreen washer & two speed wiper switch RHS to LD20000	216949	39453A	39453A/B		Not Serviced
Windscreen washer & two speed wiper switch LHS to LD20000	216950	39452A	39452A/B		Obsolete
Windscreen washer & two speed wiper switch USA to LD20000	218667		39875A		
Windscreen washer & two speed wiper switch RHS from LD20000	219062			39925A	
Windscreen washer & two speed wiper switch LHS from LD20000	219063			39927A	Not Serviced
Windscreen washer & two speed wiper switch USA from LD20000	219071			39926A	Obsolete
Headlamp dip & flash, direction indicator & horn switch RHS to LD20000	216947	39451D	39451D/E		30502
Headlamp dip & flash, direction indicator & horn switch LHS to LD20000	TKC450	39450D	39450D/E		Not Serviced
Headlamp dip & flash, direction indicator & horn switch RHS from LD20000	219154			39974A	Not Serviced
Headlamp dip & flash, direction indicator & horn switch LHS from LD20000	219155			39975A	