


REAR AXLE SHAFTS



NOTE:

Items marked thus * are part of + Rear Hub and Half Shaft Assy Part No. 308620	2 off
Items marked thus * are part of + Rear Hub and Half Shaft Assembly RKC0448	2 off
+ Fitted up to Commission No. only	2 off
+ Fitted from Commission No. and future	2 off

REAR AXLE

02-47 Rear Axle Shafts	Part No	
	Triumph	Rimmer Bros
Bolt	107960	107960
Core plug	118826	118826
Oil seal housing	128638	128638
Wheel stud - to commission no LD32900	132317	132317
Tab washer	134233	134233
Washer	134234	134234
Upper mounting bush	134235	134235
Lower mounting bush	134236	134236
Bearing	134465	134465
Adjuster - to commission no LD32900	134584	ULC2188
Nut - lock, to commission no LD32900	134585	134585
Woodruff key	134591	134591
Rear hub housing - to commission no LD32900	137496	137496
Stoneguard - to commission no LD32900	137497	137497
Stud	137601	105124
Spacer - to commission no LD32900	138272	138272
Seal	138523	138523
Nut	138563	21A79
Nut - lock, to commission no LD32900	138861	138861
Washer - lock	139043	142333
Washer - tab, to commission no LD32900	139057	139057
Gaiter clip - to commission no LD32900	140606	
Gaiter clip - to commission no LD32900	140607	
Gaiter - to commission no LD32900	140753	140753
Woodruff key	143280	143280
Inner axle shaft - LH	149378	149378
Inner axle shaft - RH	149379	149379
Flange	149409	149409
Outer drive shaft flange	210979	210979
Inner dust boot - to commission no LD32900	213844	213844
Hub & outer shaft assembly - to commission no LD32900	308620	311914R
Rear cover	309033	309033
Rear mounting plate	311268	311268
Cotter pin	510408	510408
Inner bearing - to commission no LD32900	GHB101	GHB101
Outer bearing - to commission no LD32900	GHB112	GHB265
Inner hub seal - to commission no LD32900	GHS131	GHS131
Outer hub seal - to commission no LD32900	GHS133	GHS133
Nut - nyloc	HN2009	GHF202
Setscrew	HU0806	GHF120
Setscrew	HU808	GHF103
Split pin - from commission no LD32900	PC0013	PC13
Hub & outer shaft assembly - from commission no LD32900	RKC0448	311914R
Nut - nyloc, to commission no LD32900	TN3208	TN3208
Nut - nyloc	TN3209	TN3209
Washer - lock	WL0208	GHF332
Washer - to commission no LD32900	WM0063	WM63