


BRAKE MASTER CYLINDER



NOTE
 309120 TANDEM BRAKE MASTER CYLINDER AND SERVO ASSEMBLY
 519177 MASTER CYLINDER ASSEMBLY
 Parts marked thus * are part of REPAIR KIT 519060

BRAKES

02-63 Master Cylinder	Part No	
	Triumph	Rimmer Bros
Tandem brake master cylinder & servo assembly	309120	
Supply tank lock washer	501196	
Spring	514149	
Pin	514154	
Stop	514157	
Circlip	514158	
Washer	514159	
Bearing	514160	
Retainer	514163	
Spring	514164	
Spring	514165	
Retainer	514166	
Ring	514167	
Cover gasket	515344	
Piston washer	516292	
Outlet fitting	518708	
Supply tank seal	518710	
Cup	518712	
Seal	518713	
Filler cap seal	518714	518715S
Filler cap	518715	518715
Insert	518716	
Valve trap assembly	518719	
Master cylinder supply tank	518755	GMC218RES
Piston assembly	519042	
Brake master cylinder service kit	519060	519060
Piston	519072	
Cup retainer	519073	
Main cup	519074	
Main cup	519075	
Brake master cylinder assembly	519177	GMC218
Spring	519178	