

## ELECTRICAL EQUIPMENT

05-26 Headlamps Right Hand Steering	Quantity	Part No			
		Triumph	Lucas		Rimmer Bros
			1971	1973	
Inner main beam headlamp assembly	2	311840	60160A	60110	311840
Headlamp rim	2	511598	54520356	54524588	511598A
Screw	4	507086	186137	186137	GHF425
Inner main beam headlamp glass bowl	2	GLU538	54224935	54524935	GLU538
Bulb	2	GLB448	448	448	GLB448
Rim seating assembly	2	518044	54523537	54524590	
Sealing sleeve	4	518081	54524040	54524720	
Gasket	2	511602	54520217	54520217	511602
Nut - lock	6	625536			570779
Bowl	2			54525488	RS1114
Outer dipped beam headlamp assembly	2	311830	60161A	60392	311830
Headlamp rim	2	511598	54520356	54524588	511598A
Screw	4	507086	186137	186137	GHF425
Outer dipped beam glass bowl	2	GLU537	54524936	54526184	GLU537
Bulb	2	GLB448	448	448	GLB448
Rim seating assembly	2	518082	54523538	54525683	
Sealing sleeve	4	518081	54524040	54524720	
Gasket	2	511602	54520217	54520217	511602
Nut - lock	6	625536			570779
Bowl	2			54525488	RS1114