

ELECTRICAL EQUIPMENT

05-27 Headlamps Left Hand Steering - except France & USA	Quantity	Part No			
		Triumph	Lucas		Rimmer Bros
			1971	1973	
Inner main beam headlamp assembly	2	311841	59986A/B	60215	311841
Headlamp rim	2	511598	54520356	54524588	511598A
Screw	4	507086	186137	186137	GHF425
Inner main beam sealed beam unit	2	GLU105			GLU105
Inner main beam headlamp glass bowl			54524269	54524269	
Bulb retaining spring	2		54522993	54522993	
Bulb	2		410	410	
Rim seating assembly	2	518044	54253537	54524590	
Sealing sleeve	4	518081	54524040	54524720	
Gasket	2	511602	54520217	54520217	511602
Nut - lock	6	625536			570779
Bowl	2		54520207	54525488	RS1114
Outer dipped beam headlamp assembly	2	311831	59988A	60216	311831
Headlamp rim	2	511598	54520356	54524588	511598A
Screw	4	507086	186137	186137	GHF425
Outer dipped beam glass bowl	2	518817	54524078	54524078	GLU526
Bulb retaining spring	2	511611	54522993	54522993	511611
Bulb	2	GLB411	410	410	GLB410
Rim seating assembly	2	518082	54523538	54524589	
Sealing sleeve	4	518081	54524040	54524720	
Gasket	2	511602	54520217	54520217	511602
Nut - lock	6	625536			570779
Bowl	2		54520207	54525488	RS1114