

ELECTRICAL EQUIPMENT

05-28 Headlamps Left Hand Steering - USA	Quantity	Part No			
		Triumph	Lucas		Rimmer Bros
			1971	1973	
Inner main beam headlamp assembly	2	311842	58602A/H	58602	311842
Headlamp rim	2	511598	54520356	54524588	511598A
Screw	4	507086	186137	186137	GHF425
Inner main beam sealed beam unit	2	511606		54521334	DRC1861A
Adaptor	2		553738	553738	
Rim seating assembly	2	518044	54523537	54524590	
Sealing sleeve	4	518014	54520216	54524720	
Gasket	2	511602	54520217	54520217	511602
Nut - lock	6	625536			570779
Bowl	2		54520207	54525488	RS1114
Outer dipped beam headlamp assembly	2	311832	58603A/H	58603	311832
Headlamp rim	2	511598	54520356	54524588	511598A
Screw	4	507086	186137	186137	GHF425
Outer dipped beam sealed beam unit	2	511607		54521335	DRC1862A
Adaptor	2		553738	553738	
Rim seating assembly	2	518082	54523538	54524589	
Sealing sleeve	4	518081	54520216	54524720	
Gasket	2	511602	54520217	54520217	511602
Nut - lock	6	625536			570779
Bowl	2		54520207	54525488	RS1114