

## ELECTRICAL EQUIPMENT

05-29 Headlamps Left Hand Steering - France	Quantity	Part No			
		Triumph	Lucas		Rimmer Bros
			1971	1973	
Inner main beam headlamp assembly	2	311844	59989A	60215	311844
Headlamp rim	2	511598	54520356	54524588	511598A
Screw	4	507086	186137	186137	GHF425
Inner main beam headlamp glass bowl	2	518816	54524269	54524269	GLU525
Bulb retaining spring	2	511611	54522993	54522993	511611
Bulb	2	GLB411	411	411	GLB411
Rim seating assembly	2	518044	54523537	54524590	
Sealing sleeve	4	518081	54524040	54524720	
Gasket	2	511602	54520217	54520217	511602
Nut - lock	6	625536			570779
Bowl	2		54520207	54525488	RS1114
Outer dipped beam headlamp assembly	2	517845	59991A	60216	517845
Headlamp rim	2	511598	54520356	54524588	511598A
Screw	4	507086	186137	186137	GHF425
Outer dipped beam glass bowl	2	518817	54524078	54524078	GLU526
Bulb retaining spring	2	511611	54522993	54522993	511611
Bulb	2	GLB411	411	411	GLB411
Rim seating assembly	2	518082	54523538	54524589	
Sealing sleeve	4	518081	54524040	54524720	
Gasket	2	511602	54520217	54520217	511602
Nut - lock	6	625536			570779
Bowl	2		54520207	54525488	RS1114