

ELECTRICAL EQUIPMENT

05-48 Seat Sensor	Quantity	Part No			
		Triumph	Lucas		Rimmer Bros
			1971	1973	
Sensor switch	1	158534			
Rivet - bifurcated	2	RB5208			
Washer - plain, light	2	WP109			