

## TRIUMPH & LUCAS PART NUMBERS

05-29 Headlamps Left Hand Steer (LHS) - France	Part No				
	Triumph	Lucas			
		1971	1972	1973	1987 Supersession
Headlamp rim	511598	54520356			54524588
Headlamp rim	511598		54524588	54524588	
Rim seating assembly	518044	54523537			Obsolete
Rim seating assembly	518044		54524590	54524590	54528182
Body		54520207			
Body			54525488	54525488	
Inner main beam headlamp assembly	311844	59989A			LLB411 61154
Inner main beam headlamp assembly	311845		60215 & 411	60215 & 411	LLB410 61153
Inner main beam headlamp light unit	518816	54524269	54524269	54524269	LUB220
Rim seating assembly	518082	54523538			Obsolete
Rim seating assembly	518082		54524588	54524588	
Outer dipped beam headlamp assembly	517845	59991A			LLB411 61153
Outer dipped beam headlamp assembly	517845		60216 & 411	60216 & 411	LLB410 61153
Outer dipped beam light unit	518817	54524078	54524078	54524078	LUB210
Bulb	GLB411	411	411	411	LLB411
Bulb retaining spring	511611	54522993	54522993	54522993	Not Serviced
Screw	507086	186137	186137	186137	Not Serviced
Sealing sleeve	518081	54524040			
Sealing sleeve	518081		54524720	54524720	Not Serviced
Gasket	511602	54520217	54520217	54520217	Not Serviced