

TRIUMPH & LUCAS PART NUMBERS

05-37 Windscreen Wiper Arms & Blades	Part No				
	Triumph	Lucas			
		1971	1972	1973	1987 Supersession
Windscreen wiper blade - driver's side, RHS	GWB178	54703746	54703746	54703746	Not Serviced
Windscreen wiper blade rubber assembly		54704035	54704035	54704035	WDB140A2
Windscreen wiper arm - driver's side, RHS	160049	54703744	54703744	54707823	Not Serviced
Wheelbox assembly - RHS	519933	72837D (72866 & 54706131)	72837D (72866 & 54706131)	72837D (72866 & 54706131)	
Windscreen wiper blade - passenger's side, RHS	GWB152	54701324	54701324	54701324	WBB142
Windscreen wiper blade rubber assembly		54704035	54704035	54704035	WDB140A2
Windscreen wiper arm - passenger's side, RHS	150637	54703747	54703747	54703747	Not Serviced
Wheelbox assembly	519933	72838B (72866 & 54706132)	72838B (72866 & 54706132)	72838B (72866 & 54706132)	Not Serviced
Windscreen wiper arm - driver's side, LHS	160050	54703745	54703745	54707824	Not Serviced
Windscreen wiper arm - passenger's side, LHS	150634	54703810	54703810	54703810	
Tubing - extension	626555	54702605	54702605	54702605	
Tubing - wheelbox to wheelbox	814498	54703660	54703660	54703660	60600539
Tubing - wiper motor to wheelbox, RHS	814496	54703658	54703658	54703658	60600539
Tubing - wiper motor to wheelbox, LHS	814497	54703659	54703659	54703659	60600539
Windscreen wiper rack assembly (50 29/32" length)	RTC1149	54701536	54701536	54701536	