

TRIUMPH & LUCAS PART NUMBERS

05-46 Console Switches	Part No				
	Triumph	Lucas			
		1971	1972	1973	1987 Supersession
Heater blower switch	131812	39257A		39257A	Obsolete
Heated backlight switch	130544	31869		31869	SPB104
Interior light switch	519916	39336A			Not Serviced
Interior light switch - later	519916	39693A	39693A	39693A	Not Serviced