

ENGINE

02-18 Oil Pump & Distributor Drive Shaft	Quantity	Part No	
		Triumph	Rimmer Bros
Oil pump assembly	1	215573	GLP106
Oil pump drive shaft	1	144764	144764
Oil seal	1	145861	145861
Oil pump gasket	1	157348	
Oil seal	1	517721	
Shaft & rotor assembly	1	517723	
Oil pump cover assembly	1	152159	
End plug	1	152161	
End plug seal	1	517722	
Plunger spring	1	156378	
Plunger	1	152157	
Retaining screw	2	517720	
Split pin	1	517719	
Bolt	4	HB817	BH605181
Washer - spring	4	WL208	GHF332
Relief valve kit	1		RTC2157
Oil pick-up assembly	1	149385	149385
Gasket	1	147458	147458
Bolt	2	HB709	SH604091
Washer - plain	2	WP23	GHF300